



Site Photo 7 – Stacked 55-gallon Drums Near Southwest Corner Of Subject Property



Site Photo 8 – 55-Gallon Drums Labeled Sodium Hydroxide Near Center of Subject Property.



Site Photo 9 – Abandoned Concrete Line Sludge Drying Beds in Northern Portion Of Subject Property



Site Photo 10 – Mounds of Soil Near Sludge Drying Beds From Mitigation Activity